

Shiawassee Stream Team Site Report Card

Site: **N. State Drain**
County: Shiawassee
Sampling Date: 10/10/2009
Site ID: SH01

Location: T8N, R2E, Sec. 4
Township: Rush

Overall Score: 39

Overall Rank: Good

Water Color: Clear

Stream Type: Drain

Erosion present: Moderate erosion, undercut banks, erosion from recent auto accident.



Photo by: H. Frei, TNC.

Sensitive species present: Common: Caddisfly larvae, mayfly nymphs