



Shiawassee Stream Team Site Report Card

Site: North State Drain

Sampling Date: 5/1/2010

Site ID: SH01

Location: T8N, R2E, Sec. 4

Township: Rush

Overall Score: 50.8

Overall Rank: Good

Water Color: Clear

Stream Type: Drain

Erosion Present: Moderate erosion,
undercut banks.




Photo: J. McMillon, FOSR.

Sensitive species present: Common: mayfly nymphs. Rare: caddisfly larvae, gilled (right-handed) snails, stonefly nymphs.

